



<b>Contract No.</b> 9214	<b>Station</b> Project Limits	<b>Mile/Line:</b> Pier 2 and Pier 5 Bridge 154N	<b>C/S</b> 
<b>Staked by</b> 	<b>Date</b> 	<b>Work Started Date</b> 9/9/2019	<b>Work Completed Date</b> 
<b>Calculated by</b> Karlee Morrier	<b>Date</b> 9/23/2019	<b>Checked by</b> E. Knudson	<b>Inspector</b> Karlee Morrier
			<b>Date</b> 9/23/19

**HINGE CONCRETE REPAIR  
BID ITEM #22  
UNIT: S.Y.**

**GROUP 3**

**7-23-19: 154N Pier 2 Hinge; 127.62  
Pier 5 Hinge; 92.25**

Total = **219.87 S.Y.**

I measured the square footage of delaminated concrete that was chipped out with a engineer's scale tape.

Material Luster Seal WB 300 is approved per Ram 0026 but has not been posted to the ROM. 7.5 Gallons of this material was used for both hinges under Bridge 154N.

63 bags of the Eucorepair V100 was used for both hinges under Bridge 154N.

Item Num	Material Brand Name/Model Type	Manufacturer	Brand Name/Model Type	RAMS/QPL Ref. No.	Appr/Acc Code	Basis of Accept
022.03.01	Patching Mortar Extended with Aggregate	Euclid	EucoRepair V100	RAM-0020.3	8	/ Satisfactory test report for air content & compressive strength performed once per shift

Item Num	Item Description	Grp	Date Work Complete	Unit	Quantity	Ledger Entry No.	Posted By Init.	Posted By Date	Checked By Init.	Checked By Date	Est. No.
0022	HINGE CONCRETE REPAIR	3	9/20/2019	S.F.	219.9	660	EK	09/27/19			17

**Attachments**

File Attachment